

Rutherford Decorator

Model 6CD4-A-10

Serial # 14530

Spare part list



Microsoft Excel
Worksheet

MAJOR ASSEMBLY PARTS		
#	Part #	Description
1	CD2-A-43	OVEN SPROCKET WITH SHEAR PIN
2	CMP-A-55	CARRIAGE TRIP ASSEMBLY
3	CD4-A-48	OVEN CHAIN DRIVE ASSEMBLY
4	CD4-A-30	VACUUM STARWHEEL INFED ASSEMBLY
5	8CD7-A-29	SUPPORT SUB ASSEMBLY (LINEAR ASSY)
6	CD4-A-21	VALVE ASSEMBLY
7	CD4-A-27	TRANSFER ASSEMBLY
8	CMP-A-50	MICRO CARRIAGE ADJUSTMENT ASSEMBLY
9	6CD2-A-93	INKER ASSEMBLY
10	5CD2-A-94	FOUNTAIN ROLLER ASSEMBLY
11	CD2-A-92	PLATE CYLINDER ASSEMBLY
12	CD4-A-65	SPINDEL ASSEMBLY
13	CD4-A-20	SPINDEL DISK ASSEMBLY
14	6CD4-A-15	MAIN DRIVE ASSEMBLY
15	CMP-A-406	ADJUSTABLE MAIN DRIVE MOTOR
16	5CD4-A-300	ENCODING TIMING LAYOUT
17	6CD2-A-350	WATER COOLED MANIFOLD ASSEMBLY
18	5CD4-A-40	EIGHT SEGMENT BLANKET CYLINDER ASSEMBLY
19	5CD4-A-41	EIGHT SEGMENT BLANKET CYLINDER ASSEMBLY AND SHAFT SUB ASSEMBLY
















Machine stripped ready for moving





Machine stripped ready for moving



**Inkers tripped and cleaned
Machine stripped ready for
moving**





Mandrels blocks stripped and cleaned